CAR TRUTH

Comprehensive
Car Inspection Report

Thorough inspection with

140+ quality checks

Precise insights from

experienced technicians

Trusted by

over 600,000 customers



IND ** ** ******

Hyundai Verna

SX1.5VTVT IVT | 2020 | AT | Petrol

Inspection location: Gurgaon

Report generated on: 24 Apr, 2024

CARS24 TRUST

10M +	200 +	1M+
Cars Inspected	Cities present	Cars sold

Content of report

01 Your report at a glace

Overview of your overall car condition




02 Inspection summary

Category wise ratings and condition



03 Detailed Evaluation of each category

1. Exterior & Tyres
2. Engine & Transmission
3. Steering, Suspension & Brakes
4. Air Conditioning
5. Electricals & Interiors
6. Other Details



04 Past service records

Detailed history of maintenance, repairs, odometer tampering and accident reports



05 OEM installed features & specs

1. Safety
2. Fuel & Performance
3. Entertainment & Communication
4. Dimensions & Capacity
5. Engine, Transmission & Brakes
6. Comfort & Convenience



SAMPLE REPORT

CAR TRUTH BY CARS24

Advanced report



Hyundai Verna

SX 1.5 VTVT IVT | 2021 | Automatic | Petrol

Overall Rating **4.2/5** **Excellent**

Odometer reading
72,553 kms

Estimated Value
₹9.5 L - ₹10.5 L

4 Challans Pending — Check challans

Ownership no.	Blacklisted	Fitness validity
02	false	06 Jul, 2036

Health report summary

At CARS24, we inspect cars thoroughly across 140 parameters, ensuring the highest quality. Your car has been inspected and is non-accidental, non-flooded, and non-tampered.

- The car's engine and transmission are in good working condition.
- The exterior has minor scratches and dents, but no major damage.
- The interior is in good condition with minor wear and tear.

Overall, your car is in good condition with minor cosmetic issues.

SAMPLE REPORT

Ownership & Documentation

Owner: [redacted]	Insurance validity & Type: [redacted]
Reg. State/RTO: [redacted]	Estimated kms driven / yr: **20,724**
Year purchased (1st owner): **2021**	PUC validity: **26 Jul, 2025**
Type of owner: **Individual**	Hypothecation: **Yes**

Transferability details

Blacklisted: **No**

RTO NOC Issued: **30 June, 2014**

Party Peshi Applicability: **No**

Hypothecation & Financier Name: **Yes & HDFC Bank Pvt. Ltd.**

Vehicle modification

Converted (Commercial ownership to private): **No**

Migration (Re-registered in another state): **No**

Adapted for Special Use (Example differently abled): **No**

Legal history details

Criminal cases: **1**

Civil cases: **1**

Road accidents: **None reported**

Theft cases: **None reported**

Compensation cases: **None reported**

Other cases: **None reported**

SAMPLE REPORT

Criminal case

Accident date: 16 June,2023

Filing date: 15 June, 2023

Place: New Delhi, Delhi

Violation: Minor Traffic Violation

Legal position: Accused

FIR number: FIR123/2023

FIR summary: Signal jumping incident

Acts/Sections: IPC, Section 279

Civil case: Disposed

Filing date: 1 July, 2023

Disposed date: 1 December, 2023

Place: New Delhi, Delhi

Violation: Contract dispute

Legal position: Respondent

CNR number: CNR123/2023

Disposal summary: Settled by mutual agreement

Order judgement summary: Case disposed with mutual settlement

Challan history

⚠ Total 4 pending challans worth ₹10,000 — Pay now >

2025

ⓘ Total challans: 2 ⚠ Pending: 2

Date	Offence	Challan no.	Amount	Status
12 Jan, 2025	OVER SPEED (Light Motor Vehicle) (112/183 MV ACT)+2 more	1234567890	₹2,500	Pending
12 Jan, 2025	Improper parking	1234567890	₹2,500	Pending

2023

ⓘ Total challans: 1

Date	Offence	Challan no.	Amount	Status
12 Jan, 2023	Improper parking	1234567890	₹2,500	Moved to physical court

2014

ⓘ Total challans: 4 ⚠ Pending: 2

Date	Offence	Challan no.	Amount	Status
12 Jan, 2014	OVER SPEED (Light Motor Vehicle) (112/183 MV ACT) +2 more	1234567890	₹2,500	Moved to physical court
12 Jan, 2014	Improper parking	1234567890	₹2,500	Paid
12 Jan, 2014	Improper parking	1234567890	₹2,500	Moved to physical court
12 Jan, 2014	Improper parking	1234567890	₹2,500	Paid

SAMPLE REPORT

Inspection summary

This section provides a comprehensive evaluation of the most recent car assessment, meticulously divided into five key categories to offer an in-depth and accurate overview.

Exterior & Tyres

The exterior of the car has scratches and some parts have been repainted. The tyres have a tread depth of 3-5mm.

3.7/5
Neutral

Engine & Transmission

The engine is in good condition. There are no issues with blow-by, engine sound, or exhaust smoke. However, the engine oil is dirty.

4.5/5
Excellent

Steering, Suspension & Brakes

Your car's steering, suspension, and brakes are all in good condition. There are no issues that need immediate attention.

4.5/5
Excellent

Air Conditioning

The air conditioning in your car is working perfectly. The AC, heater, and climate control are all functional.

4.7/5
Excellent

Electricals & Interiors

Your car has all the electrical features working well, including power windows, airbags, music system, and a reverse camera. The interior is in good condition with leather seats and a sunroof.

4.4/5
Excellent

SAMPLE REPORT

Vehicle images

















REPORT

CAR TRUTH BY CARS24

Advanced report

Exterior & Tyres | Engine & Transmission | Electricals & Interiors | Steering, Suspension & Brakes | Air Condition | Other Details

01. Exterior & Tyres

Perfect parts: 26 | Imperfect parts: 25 | Estimated repair cost: ₹10,000

Parameters	Perfect	Imperfect
Boot Floor	✓	
Pillar LHS A	✓	
Pillar LHS B	✓	
Pillar LHS C	✓	
Pillar RHS A	✓	
Pillar RHS B	✓	
Pillar RHS C	✓	
Apron LHS	✓	
Apron RHS	✓	
Apron RHS LEG	✓	
Apron LHS LEG	✓	
Firewall	✓	
Cowl Top	✓	
Upper Cross Member (Bonnet Patti)	✓	
Front Show	✓	
Lower Cross Member	✓	
Radiator Support	✓	

SAMPLE REPORT

CAR TRUTH BY CARS24

Advanced report

Exterior & Tyres | Engine & Transmission | Electricals & Interiors | Steering, Suspension & Brakes | Air Condition | Other Details

Parameters	Perfect	Imperfect
Head Light Support	✓	
Windshield Rear	✓	
Light LHS Taillight	✓	
Light LHS Fog Light	✓	
Light RHS Fog Light	✓	
ORVM - Manual / Electrical LHS	✓	
Tyre Spare Tyre	✓	
Grill	✓	
Is the Car Waterlogged?	✓	
Roof		!
Bonnet/Hood		!
Dicky Door / Boot Door		!
Quarter Panel LHS		!
Quarter Panel RHS		!
Fender LHS		!
Fender RHS		!
Running Border LHS		!
Running Border RHS		!
Door LHS Front		!

SAMPLE REPORT

CAR TRUTH BY CARS24

Advanced report

Exterior & Tyres | Engine & Transmission | Electricals & Interiors | Steering, Suspension & Brakes | Air Condition | Other Details

Parameters	Perfect	Imperfect
Door LHS Rear		!
Door RHS Front		!
Door RHS Rear		!
Windshield Front		!
Light LHS Headlight		!
Light RHS Headlight		!
Light RHS Taillight		!
Bumper Front		!
Bumper Rear		!
ORVM - Manual / Electrical RHS		!
Alloy Wheel		!
LHS Front Tyre		!
LHS Rear Tyre		!
RHS Front Tyre		!
LHS Rear Tyre		!

SAMPLE REPORT




Roof: No Dents, Scratched



Bonnet/Hood: No Dents, Scratched




Dicky Door / Boot Door: No Dents, Scratched




Quarter Panel LHS: No Dents, Repainted




Quarter Panel RHS: No Dents, Repainted



Fender LHS: No Dents, Scratched, Repainted



Fender RHS: No Dents, Repainted



Running Border LHS: No Dents, Scratched, Repainted

SAMPLE



Running Border RHS: No Dents, Repainted



Door LHS Front: No Dents, Scratched, Repainted



Door LHS Rear: No Dents, Repainted, Scratched



Door RHS Front: No Dents, Repainted



Door RHS Rear: No Dents, Repainted



Windshield Front: Scratched

SAMPLE REPORT



Light LHS Headlight: Scratched



Light RHS Headlight: Scratched



Light RHS Taillight: Scratched



Bumper Front: Scratched, Dented



Bumper Rear: Repainted



ORVM - Manual / Electrical RHS: Damaged



Alloy Wheel: Scratched



LHS Front Tyre: 70% life remaining

SAMPLE REPORT



LHS Rear Tyre: 30% life remaining



RHS Front Tyre: 70% life remaining



LHS Rear Tyre: 30% life remaining

SAMPLE REPORT

02. Engine & Transmission

Perfect parts: 11 | Imperfect parts: 01 | Estimated repair cost: ₹500

Parameters	Perfect	Imperfect
Engine	✓	
Engine Sound	✓	
Exhaust Smoke	✓	
Engine Permissible Blow by (Back Compression)	✓	
Clutch	✓	

Parameters	Perfect	Imperfect
Gear Shifting	✓	
Engine Oil Level Dipstik	✓	
Battery	✓	
Coolant	✓	
Sump	✓	
Engine Oil		!

03. Electricals & Interiors

Perfect parts: 14 | Imperfect parts: 00 |

Parameters	Perfect	Imperfect
4 Power Windows	✓	
Airbag Feature	✓	
Music System	✓	
Leather Seat	✓	
Sunroof	✓	
Steering Mounted Audio Control	✓	
ABS	✓	
Rear Defogger	✓	

SAMPLE REPORT

Parameters	Perfect	Imperfect
Reverse Camera	✓	
Electrical	✓	
Interior	✓	
Parking Sensor	✓	
No. Of Airbags	✓	
No. Of Power Windows	✓	

Parameters	Number
No. Of Airbags	2
No. Of Power Windows	4

SAMPLE REPORT

04. Steering, suspension & Brakes

Perfect parts: 02 | Imperfect parts: 01 | Estimated repair cost: ₹4,000

Parameters	Perfect	Imperfect
Steering	✓	
Suspension		!
Brake	✓	

05. Air Conditioning

Perfect parts: 03 | Imperfect parts: 0

Parameters	Perfect	Imperfect
AC Cooling	✓	
Heater	✓	
Climate Control AC	✓	

06. Other Details

Available : 03 | Not Available: 01

Parameters	Available	Not available
Chassis Embossing	✓	
RC Availability	✓	
Insurance Image	✓	
Duplicate Key		!

SAMPLE REPORT

Total estimated repair cost

A rough estimate of the cost required to fix identified imperfections in the car, helping you anticipate potential repair expenses before buying/selling.

Total estimated repair cost: ₹14,450

Total imperfect parts:27

Parameters	Total imperfect parts	Est. Repair Cost
Exterior & Tyres	25	₹10,000
Engine & Transmission	1	₹500
Steering, Suspension & Brakes	1	₹4,000


SAMPLE REPORT

Past service records

Viewing the service history from authorised workshops helps assess the car's maintenance, check for any accidents, plan future care, and build confidence in its reliability and boost confidence in ownership.

Last odometer reading (km at OEM)	Total loss reported	Accidental history
1,00,000 Km	No	Yes

Service and maintenance summary



This vehicle is serviced regularly

The car has been serviced 10 times in 5 years, with no gap exceeding 9 months.


Vehicle Details	Value	Remark
Total services at authorised service centre	6	✓
Last service at authorised service centre	20 Oct, 2024	✓
Structural damage	No	!
Airbag deployment	No	✓
Flooded car	No	✓
Odometer tampering	Yes	!
Gear/Transmission repair	No	!

SAMPLE REPORT

✓ Positive Condition (Good/No Issues) ! Neutral Condition (Minor Concern) ! Negative Condition (Potential Issue)


Odometer reading

METHODOLOGY Odometer tampering is identified if the next service record has a lower odometer reading than the previous one.




Odometer has been tampered once

The odometer has been tampered 01 time till now before the 7th service of the car. Since the odometer reading went down from S6 to S7.



SAMPLE REPORT

Accident history



Major and minor accident reported in this car

There have been 6 major and minor accidents reported for this car.

Service records

Service visit number	Service date	Odometer reading (Kms)	Part details
S1	8 Jan, 2023	5,000	Spark Plug, Air Filter, Brake Oil, Grease Caliper Assy, Coolant, Boot Shift Lever (Black), Plug Oil Drain Work, Gear Knob, Brake Fluid GC1500AA (500 ML Pack)
S2	9 Mar, 2023	10,000	Engine oil replaced, Air filters replaced, Wheel Balancing & Alignment
S3	15 Jun, 2023	20,000	Bulbs change
S4	20 Nov, 2023	30,000	Engine oil replaced, Air filters replaced, Wheel Balancing & Alignment
S5	21 Jan, 2024	50,000	Engine oil replaced, Air filters replaced, Wheel Balancing & Alignment
S6	19 Mar, 2024	1,00,000	Engine oil replaced, Air filters replaced, Wheel Balancing & Alignment
S7	21 Jan, 2024	1,50,000	DCT - ECM Flashing
S8	20 Jul, 2024	1,75,000	Spark Plug, Air Filter, Brake Oil, Grease Caliper Assy, Coolant, Boot Shift Lever (Black), Plug Oil Drain Work, Gear Knob, Brake Fluid GC1500AA (500 ML Pack)

SAMPLE REPORT

OEM installed features & specs

Understanding the features and specifications of the **Hyundai Verna** is essential to ensure it aligns with your preferences, needs, and lifestyle, helping you find the perfect automotive match.

Power window	Airbags	Seating capacity
Front & rear	**04**	**05**

Safety

Parameters	Metric
Front Fog Lights	**Yes**
ISOFIX-Child Seat Anchor Points	**Yes**
Anti-lock Braking System (ABS)	**No**
Central Locking	**Keyless Entry**
Rear Defogger	**Yes**
Airbags	**04**


Fuel & Performance

Parameters	Metric
Max power (bhp)	**81.80**
Max torque (Nm)	**114.7**
Fuel tank capacity (lit)	**24**
Emission Standard	**BSIV**

SAMPLE REPORT


Entertainment & Communication

Instrument panel type	360 degree camera	Speaker brand
Analogue & digital	**Yes**	**JBL**




SAMPLE REPORT

Interior & Exterior



Dimensions & Capacity



Engine, Transmission & Brakes

Parameteres	Metric
Gear Box- No. of Gears	**04**
Displacement (cc)	**1800**
Transmission type	**Manual**
Cylinders	**02**
Break type (rear)	**Drum**
Break type (front)	**Drum**
Number of disc brakes	**02**

SAMPLE REPORT

Comfort & Convenience

Parameteres	Metric
Seat upholstery (cc)	**1800**
Auto climate control	**Yes**
Wireless charging pad	**Yes**
Steering wheel material	**Alloy & Synthetic Leather**
Smart Card/Smart Key	**Yes**
Top model	**Yes**

Parking sensors

No

Rear AC

Yes

Power windows

Front & rear

Steering adjustment

Tilt & telescope

Driver seat adjustment

Manual

Cruise control

No

Air conditoner

Yes

Push button start

Yes

SAMPLE REPORT

Thank you for choosing us!


We truly appreciate your decision to prioritize the safety and maintenance of your vehicle. By opting for a thorough inspection, you're ensuring not only the longevity of your car but also peace of mind for you and your loved ones.
Should you have any questions about the inspection report or need further assistance, please don't hesitate to reach out. We're here to help and ensure your vehicle remains in top condition.
Thank you once again for your trust and patronage.

Other services by


CHALLAN ↗

SERVICE HISTORY ↗

PERSONAL LOAN ↗



SAMPLE REPORT



Buying, selling, and financing pre-owned cars is now easier than ever!

4.3 ★★★★½
194K ratings • Google Play

4.5 ★★★★★
24.1K ratings • App Store

4.1 ★★★★☆
1K ratings • Trustpilot

Experience CARS24 App on mobile

GET IT ON Google Play | Download on the App Store

Keep in touch

care@cars24.com

Disclaimer: Service provided by Cars24 is conducted to the best of our ability and knowledge at the time of inspection. Cars24 shall not be liable for any direct, indirect, incidental or consequential damages rising in connection with any defect, damages, or misrepresentation related to the inspected vehicle. For further details, please refer to our T&Cs