

Comprehensive Car Inspection Report




Thorough inspection with
140+ quality checks



Precise insights from
experienced technicians



Trusted by
over 600,000 customers



BMW X1

SDRIVE 20D | 2012 | AT | Diesel

Inspection location: Ahmedabad

Report generated on: 12 Feb, 2025



10M +
Cars
Inspected

200 +
Cities
Present

1M +
Cars
Sold

**BMW X1**

SDRIVE 20D | 2012 | Automatic | Diesel

Overall
Rating**3.8/5****Neutral**

Odometer reading

[REDACTED]



No Challan on this vehicle



Ownership no.

03

Blacklisted

No

Hypothecation

Yes**Health report summary**

At Cars24, we inspect cars across 140 parameters, including a detailed review of the last car service, assessment of potential damages to crucial parts, and an overall aesthetic check.

- The car's engine has a major sound issue.
- The car's suspension has an abnormal noise.
- The car's ORVM has a folding motor not working and the switch is broken.

The car has some issues with the engine, suspension, and ORVM, but the overall condition is fair.

**Ownership and validity details**

Owner:

[REDACTED]

Registration date:

[REDACTED]

Ownership number: **3**

Registration place:

[REDACTED]

Ownership type: **Individual**

Fitness validity:

[REDACTED]

Estimated kms/year:

[REDACTED]

PUC validity: **10 May, 2024**

Transferability details

Blacklisted: **No**

RTO NOC Issued: **No**

Party Peshi applicability at RTO: **No**

Hypothecation &
Financier Name:

Vehicle modification

Converted (Commercial ownership to private): **No**

Migration (Re-registered in another state): **No**

Adapted for Special Use (Example differently abled): **No**

Legal history details

Criminal cases: **1** 

Civil cases: **1** 

Road accidents: **None reported**

Other cases: **None reported**

Compensation cases: **None reported**

Criminal case

Accident date: 16 June,2023

Filing date: 15 June, 2023

Place: New Delhi, Delhi

Violation: Minor Traffic Violation

Legal position: Accused

FIR number: *****

FIR summary: Signal jumping incident

Acts/Sections: IPC, Section 279

Civil case

Filing date: 1 July, 2023

Disposed date: 1 December, 2023

Place: New Delhi, Delhi

Violation: Contract dispute

Legal position: Respondent

CNR number: *****

Disposal summary: Settled by mutual
agreement

Order judgement summary: Case disposed with
mutual settlement

Challan history

Total 4 pending challans

Pay now

2025

Total challans: 2

Pending: 2

Sno.	Date	Offence	Challan no.	Amount	Status
1	12 Jan, 2025	OVER SPEED (Light Motor Vehicle) (112/183 MV ACT) +2 more	*****	₹2,500	Pending
2	10 Jan, 2025	Improper parking	*****	₹2,500	Pending

2023

Total challans: 1

Sno.	Date	Offence	Challan no.	Amount	Status
3	11 Jan, 2023	Improper parking	*****	₹2,500	Paid

2014

Total challans: 4

Pending: 2

Sno.	Date	Offence	Challan no.	Amount	Status
4	12 Oct, 2014	OVER SPEED (Light Motor Vehicle) (112/183 MV ACT) +2 more	*****	₹2,500	Paid
5	9 Aug, 2014	Improper parking	*****	₹2,500	Paid
6	14 Jul, 2014	Improper parking	*****	₹2,500	Moved to physical court
7	5 May, 2014	Improper parking	*****	₹2,500	Moved to physical court

Overall summary

This section provides a comprehensive evaluation of the most recent car assessment, meticulously divided into five key categories to offer an in-depth and accurate overview.

Exterior & Tyres

The exterior of your car has scratches and minor dents. The tires have good tread depth.

3.6/5
Neutral

Engine & Transmission

The engine is in good condition. There is permissible blow-by on idle, but no major sound.

3.5/5
Neutral

Steering, Suspension & Brakes

Your steering is in good condition. The suspension has an abnormal noise, which may need attention. Your brakes are in good condition.

3.7/5
Neutral

Air Conditioning

The air conditioning system in your car is in good working order. The AC, heater, and climate control are all functioning properly.

4.5/5
Excellent

Electricals & Interiors

The car has all the electrical features working properly, but the AC direction control knob is not working. The interior is otherwise in good condition.

3.9/5
Neutral

 Vehicle Images



Exterior & Tyres

Engine & Transmission

Electricals & Interiors

Steering, Suspension & Brakes

Air Condition

Other Details

01. Exterior & Tyres

Perfect parts: 27 | Imperfect parts: 24



Parameters	Perfect	Imperfect
Boot Floor	✓	
Pillar RHS B	✓	
Pillar RHS A	✓	
Pillar RHS C	✓	
Pillar LHS C	✓	
Apron LHS	✓	
Apron RHS	✓	
Apron RHS LEG	✓	
Apron LHS LEG	✓	
Firewall	✓	
Cowl Top	✓	
Upper Cross Member (Bonnet Patti)	✓	
Front Show	✓	
Lower Cross Member	✓	
Radiator Support	✓	
Head Light Support	✓	
Windshield Rear	✓	

Exterior & Tyres

Engine & Transmission

Electricals & Interiors

Steering, Suspension & Brakes

Air Condition

Other Details

Parameters	Perfect	Imperfect
Light LHS Fog Light	✓	
Light LHS Headlight	✓	
Light RHS Fog Light	✓	
Light LHS Taillight	✓	
Light RHS Taillight	✓	
Grill	✓	
Is the Car Waterlogged?	✓	
LHS Rear Tyre	✓	
RHS Front Tyre	✓	
LHS Rear Tyre	✓	
Roof		!
Bonnet/Hood		!
Dicky Door / Boot Door		!
Quarter Panel RHS		!
Quarter Panel LHS		!
Fender RHS		!
Fender LHS		!
Pillar LHS B		!
Pillar LHS A		!
Running Border RHS		!

Exterior & Tyres

Engine & Transmission

Electricals & Interiors

Steering, Suspension & Brakes

Air Condition

Other Details

Parameters	Perfect	Imperfect
Running Border LHS		!
Door RHS Rear		!
Door RHS Front		!
Door LHS Rear		!
Door LHS Front		!
Windshield Front		!
Light RHS Headlight		!
Bumper Front		!
Bumper Rear		!
ORVM - Manual / Electrical RHS		!
ORVM - Manual / Electrical LHS		!
Alloy Wheel		!
Tyre Spare Tyre		!
LHS Front Tyre		!

Exterior & Tyres

Engine & Transmission


Electricals & Interiors

Steering, Suspension & Brakes


Air Condition

Other Details

Exterior & Tyres imperfect parts images




Roof: Scratched, Less than 3 dents and Less than 3 inches



Bonnet/Hood: Less than 3 dents and Less than 3 inches, Scratched




Dicky Door / Boot Door: Repainted, Less than 3 dents and Less than 3 inches



Quarter Panel RHS: No Dents, Repainted, Scratched



Quarter Panel LHS: No Dents, Scratched



Fender RHS: Less than 3 dents and 3 or more inches, Scratched, Repainted

Exterior & Tyres

Engine & Transmission

Electricals & Interiors


Steering, Suspension & Brakes

Air Condition

Other Details



Fender LHS: No Dents, Repainted



Pillar LHS B: No Dents, Scratched



Pillar LHS A: No Dents, Scratched



Running Border RHS: No Dents, Scratched



Running Border LHS: No Dents, Scratched



Door RHS Rear: Less than 3 dents and Less than 3 inches, Repainted, Scratched



Door RHS Front: No Dents, Scratched



Door LHS Rear: No Dents, Repainted, Scratched

Exterior & Tyres

Engine & Transmission

Electricals & Interiors

Steering, Suspension & Brakes

Air Condition

Other Details



Door LHS Front: Scratched, Less than 3 dents and Less than 3 inches



Windshield Front: Scratched, Replaced



Light RHS Headlight: Scratched



Bumper Front: Damaged



Bumper Rear: Scratched, Faded



ORVM - Manual / Electrical RHS: Scratched, Folding Motor Not Working, ORVM Switch broken and not...



ORVM - Manual / Electrical LHS: Folding Motor Not Working



Alloy Wheel: Scratched



LHS Front Tyre: 30% life remaining



02. Engine & Transmission

Perfect parts: 09 | Imperfect parts: 01



Parameters	Perfect	Imperfect
Engine	✓	
Exhaust Smoke	✓	
Clutch	✓	
Gear Shifting	✓	
Engine Oil	✓	

Exterior & Tyres

Engine & Transmission

Electricals & Interiors

Steering, Suspension & Brakes

Air Condition

Other Details

Parameters	Perfect	Imperfect
Engine Oil Level Dipstik	✓	
Battery	✓	
Coolant	✓	
Sump	✓	
Engine Sound		!



03. Electricals & Interiors

Perfect parts: 11 | Imperfect parts: 01



Parameters	Perfect	Imperfect
4 Power Windows	✓	
Airbag Feature	✓	
Music System	✓	
Leather Seat	✓	
Steering Mounted Audio Control	✓	
ABS	✓	
Rear Defogger	✓	
Electrical	✓	
Parking Sensor	✓	
No. Of Airbags	✓	

- Exterior & Tyres
- Engine & Transmission
- Electricals & Interiors
- Steering, Suspension & Brakes
- Air Condition
- Other Details

Parameters	Perfect	Imperfect
No. Of Power Windows	<div></div>	
Interior		<div></div>

Parameters	Number
No. Of Airbags	6
No. Of Power Windows	4



04. Steering, Suspension & Brakes

Perfect parts: 02 | Imperfect parts: 01



Parameters	Perfect	Imperfect
Steering	<div></div>	
Brake	<div></div>	
Suspension		<div></div>



05. Air Conditioning

Perfect parts: 03 | Imperfect parts: 0



Parameters	Perfect	Imperfect
AC Cooling	<div></div>	

- Exterior & Tyres
- Engine & Transmission
- Electricals & Interiors
- Steering, Suspension & Brakes
- Air Condition
- Other Details

Parameters	Perfect	Imperfect
Heater	✓	

Climate Control AC	✓	
--------------------	---	--



06. Other Details

Available : 02 | Not Available: 02




Parameters	Available	Not available
Chassis Embossing	✓	

RC Availability	✓	
-----------------	---	--

Insurance Image		!
-----------------	--	---

Duplicate Key		!
---------------	--	---



Chassis Embossing: Ok




Thank you for choosing us!

We truly appreciate your decision to prioritize the safety and maintenance of your vehicle. By opting for a thorough inspection, you're ensuring not only the longevity of your car but also peace of mind for you and your loved ones.

Should you have any questions about the inspection report or need further assistance, please don't hesitate to reach out. We're here to help and ensure your vehicle remains in top condition.

Thank you once again for your trust and patronage.

Other services by CAR TRUTH BY

[CHALLAN ↗](#)
[SERVICE HISTORY ↗](#)
[PRE- DELIVERY INSPECTION ↗](#)
[PERSONAL LOAN ↗](#)


Buying, selling, and financing pre-owned cars is now easier than ever!

4.5 ★★★★★
19.4K ratings • 

4.5 ★★★★★
24.1K ratings • 

4.5 ★★★★★
1K ratings • 

Experience CARS24 App on mobile



Keep in touch

 care@cars24.com



Disclaimer: Service provided by Cars24 is conducted to the best of our ability and knowledge at the time of inspection. Cars24 shall not be liable for any direct, indirect, incidental or consequential damages rising in connection with any defect, damages, or misrepresentation related to the inspected vehicle. For further details, please refer to our T&Cs