

Smart report 2.0

# Comprehensive Car Inspection Report



Thorough inspection with

140+ quality checks



Precise insights from experienced technicians



Trusted by

over 600,000 customers



## **BMW 2 Series**

2020i M Sport | 2020 | Manual | Petrol

Inspection location: Gurgaon

Report generated on: 24 Apr, 2024





## **Content of the report**

### Your report at a glace

Overview of your overall car condition



#### Inspection summary

Category wise ratings and condition

#### **Detailed Evaluation of each category**

- 1. Exterior & Tyres
- 2. Engine & Transmission
- 3. Steering, Suspension & Brakes
- 4. Air Conditioning
- 5. Electricals & Interiors
- 6. Other Details

#### **OEM installed features & specs**

- 1. Safety
- 2. Fuel & Performance
- 3. Entertainment & Communication
- 4. Dimensions & Capacity
- 5. Engine, Transmission & Brakes
- 6. Comfort & Convenience





## 😫 Health report summary





## 

This section provides a comprehensive evaluation of the most recent car assessment, meticulously divided into five key categories to offer an in-depth and accurate overview

#### Exterior & Tyres

The car's exterior has no corrosion and minor dents and some tyres have less than 50% life remaining. Similar cars also suffer from dents/corrosion or lower tyre life. Similar cars have unclean filters or leakage problems. **4.1/5** Excellent

3.5/5

Neutral

3.7/5

Neutral

4.6/5

**Excellent** 

#### Engine & Transmission Engine Engine & Transmission Engine Engine

The engine and transmission are in fairly good condition with no wiring damages. Similar cars show signs of leaks/damage.The engine and transmission are in fairly good condition with no wiring damages.

#### G Steering, suspension & Brakes

The steering, suspension and brakes perform smoothly with a little noise. Similar cars do not have noise issues. The steering, suspension and brakes perform smoothly with a little noise.

#### **Air Conditioning**

The air conditioner is in good condition and both cooling/heating work efficiently. Similar cars have unclean filters or leakage problems. Similar cars have unclean filters or leakage problems. Similar cars have unclean filters or leakage problems.

#### Electricals & Interiors

Some electricals and interiors are in poor condition and have shock or wear/tear/ cracks. Similar cars have no shock issues with minimal wear/tear. Similar cars have unclean filters or leakage problems. 2.2/5 Need servicing



Smart report 2.0 🛱

### Vehicle images



















Exterior & Tyre	s Engine & Transmission	Electricals & Interiors	Steering, Suspension & Brakes	Air Condition Other Details

## **01. Exterior & Tyres**

Perfect parts: 31 | Imperfect parts: 04

Parameters		Perfect	Imperfect
Bumper			
Bonnet/Hood		<b>I</b>	
Roof			
Fender		$\bigcirc$	
Door	LHS Rear		
Door	LHS Front		
Door	RHS Front		
Door	RHS Rear		
Pillar			
Boot Floor			
Apron			
Firewall			
Cowl Top			
Lower Cross Member			
Upper Cross Member (Bonnet Patti)			
Head Light Support			
Radiator Support		<b>S</b>	



Exterior & Tyres Engine & Transmission	Electricals & Interiors	Steering, Suspension & Brakes	Air Condition Other Details
Parameters		Perfect	Imperfect
Front Show			•
Windshield			
ORVM - Manual / Electrical			
Light			
Tyre	LHS Front		
	RHS Front		
	LHS Rear		
	RHS Rear		
Spare Tyre			
Grill			
Cowl Top			
Lower Cross Member			
Alloy Wheel			0

### Exterior & Tyres imperfect parts images







Exterior & Tyres H Engine & Transmission H Electricals & Interiors H Steering, Suspension & Brakes H Air Condition H Other Details





Exterior & Tyres Engine & Transmission	Electricals & Interiors	Steering, Suspension & Brakes	Air Condition Other Details

Perfect parts: 11   Imperfect parts: 01		بر_ي
Parameters	Perfect	Imperfect
Head Light Support		
Engine Oil Level Dipstick	0	
Battery		
Coolant	9	
Engine Oil	$\bigcirc$	
Engine Sound		•
Exhaust Smoke		•
Engine Mounting		
Engine Permissible Blow by (Back Compression)		
Reverse Camera		
Parking Sensor		
Electrical and Instrument cluster		
Navigation Chip		
Parameters	Number	
Number of Power Windows	4	
Number of Airbags	2	



		Exterior & Tyres	Engine & Transmission	Electricals & Interiors	Steering, Suspension & Brakes	Air Condition	Other Details
--	--	------------------	-----------------------	-------------------------	-------------------------------	---------------	---------------

#### Engine & Transmission imperfect parts images



<b>O3. Electricals &amp; Interiors</b> Perfect parts: 10   Imperfect parts: 00		6000
Parameters	Perfect	Imperfect
Airbag Feature	$\bigcirc$	
Music System		
Leather Seat		
Fabric Seat		
Sunroof		
Steering Mounted Audio Control		
ABS		
Rear Defogger		



Exterior & Tyres	Engine & Transmission	Electricals & Interiors	Steering, Suspension & Brakes	Air Condition	Other Details



Brake

Suspension

Steering, Suspension & Brakes imperfect parts images





erior & Tyres Engine & Transmission Electricals & Interiors	Steering, Suspension & Brakes A	ir Condition Other D
<b>05. Air Conditioning</b> Perfect parts: 03   Imperfect parts: 00		\##
Parameters	Perfect	Imperfec
AC Cooling	$\checkmark$	
Heater		
Climate Control AC		
V		
<b>06. Other Details</b> Available : 04   Not available: 00		i
Parameters	Available	Not available
RC Available	$\checkmark$	
Duplicate Key	<b>S</b>	
Insurance Image	<b>S</b>	
Chassis Embossing		



#### Smart report 2.0 🖹

Exterior & Tyres – Engine & Transm	Electricals & Interiors	Steering, Suspension & Brakes	ir Condition Other details
		REPU	



## **Set OEM installed features & specs**

Understanding the features and specifications of the **BMW 2 Series 2024 Mi Sport** is essential to ensure it aligns with your preferences, needs, and lifestyle, helping you find the perfect automotive match.



### Fuel & Performance

Parameters	Metric
Max Power (bhp)	81.80
Max Torque (Nm)	114.7
Fuel Tank Capacity (lit)	24
Emission Standard	BSIV



### **Entertainment & Communication**





## ∠<sup>7</sup> Dimensions & Capacity



## Engine, Transmission & Brakes

Parameters	Metric	
Gear Box- No. of Gears	04	
Displacement (cc)	1800	
Transmission type	Manual	
Cylinders	02	
Break type (rear)	Drum	
Break type (front)	Drum	
Number of Disc Brakes	02	



Smart report

## 🗳 Comfort & Convenience

Parameters		Metric		Remark
Seat Upholstery (cc)		1800		
Auto Climate Control		Yes		
Wireless Charging Pad		Yes		
Steering Wheel Material	Alloy & S	Synthetic Leather		
Smart Card/Smart Key		Yes		
Top Model		Yes		
Parking sensors	Rear AC		Power windows	
No ((合))	Yes		Front & rear	<b>.</b>
Steering adjustment		Driver seat adjustment		
Tilt & telescope	67	Manual		
Cruise control	Air conditoner		Push button start	
No	Yes		Yes	E.



# Thank you for choosing us!

We truly appreciate your decision to prioritize the safety and maintenance of your vehicle. By opting for a thorough inspection, you're ensuring not only the longevity of your car but also peace of mind for you and your loved ones.

Should you have any questions about the inspection report or need further assistance, please don't hesitate to reach out. We're here to help and ensure your vehicle remains in top condition.

Thank you once again for your trust and patronage.

#### Other services by us.

CHALLAN 7 SERVICE HISTORY 7 PERSONAL LOAN 7







Disclaimer: Service provided by Cars24 is conducted to the best of our ability and knowledge at the time of inspection. Cars24 shall not be liable for any direct, indirect, indirect, incidental or consequential damages rising in connection with any defect, damages, or misrepresentation related to the inspected vehicle. For further details, please refer to our T&Cs